Form 3160-5 November 1983) Formerly 9-331)	DEPARTMI	NITED STATES ENT OF THE INTE OF LAND MANAGEME	SUBMIT IN TRIPLICA (Other Instructions or RIOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS				8F 079304 6. OF INDIAN, ALLOTTER OR TRIBE NAME
			of the proposals.)	· /
OIL GAI			,	7. UNIT AGREEMENT NAME
NAME OF OPERATO			/	8. FARM OR LEASE NAME
	- Caulkin	s Oil Company		Sanchez
ADDRESS OF OPER				9. WBLL NO.
	P.O. Bo:	x 780 Farmington.	New Mexico 87499	4
See also space 17 below.)  At surface  RECEIVED				10. FIELD AND POOL, OR WILDCAT
				Basin Dakota
	990' F/1	N & 990¹ F/W	MAY 08 1985	11. SRC., T., R., M., OR BLK. AND SURVEY OR AREA
		BURE	AU OF LAND MANAGEMENT	Section 25, 26N 6W
, PERMIT NO.		15. ELEVATIONS (Show with stings	MINGTON CHISCOURCE AREA	12. COUNTY OR PARISH 13. STATE
		6654	<del></del>	Rio Arriba New Mexic
•			Nature of Notice, Report,	or Other Data
	NOTICE OF INTENTIO	N TO:	AUI	BERQUENT REPORT OF:
TEST WATER SEC	DT-OFF PCL	L OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	<del></del>	TIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZ	B ABA	NDON Zone X	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	<del></del>	NGE PLANS	(Other)	
(Other)		ig Back X	' Completion of Rec	sults of multiple completion on Well completion Report and Log form.)  ates, including cetimated date of starting any critical depths for all markers and zones perti-
4-24-85	Hearing to red held before OO	complete and comm	ingle well in Chacra Mexico.	- Mesa Verde and Dakota
•	It is now proposed to change plans and drill new well thru Dakota formation and complete new well in Mesa Verde and Dakota formations on this proration Unit.			
1	Recompletion of this well in Mesa Verde Zone with 4 1/2" casing in well create problems for successful completion.			
1	This notice is to TD. 4000'	to ask approval leaving a single	to plug and abandon completion Chacra p	Dakota Zone and plug back roducer.
]	Perforated in	Dakota Zone 7514	to 7200' with 500	holes.
	Persent condit		5# and $11.6#$ casing $6$	cemented in 2 stages.
		(approx 248 (approx 118	Cu.ft.) followed by	ith 150 sacks 12% Gel Cement y 100 sacks Latex
I hereby certify th	the foregoing is tru	e and correct		ADDOOUTD
SIGNED OLA	arles & C	Legentra	Superintendet	DATE DATE
(This space for P	ederal or State officer	PETTEIN		
APPROVED BY _ CONDITIONS OF	APPROVAL IF ANY	MAY 09 1985 DIV.		MAY 8 1985
	F. 10-28 6	SAY U		IKM UT IIIDO ALLO
		L COSSeg Instruction		1000

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency or the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

2nd stage thru tool at 5376' with 400 sacks 12% Gel (Approx 660 Cu.Ft.) followed by 100 sacks Neat Cement. (Approx 118 Cu.Ft.)

Temperature Survey shows cement top at 3200'.

4 1/2" casing perforated in Dakota Zone 7200' to 7514' with 500 holes.

Proposed Plug and Abandon and Plug Back as follows:

Clean out to TD 7545', spot cement 7545' to 7000'.

Spot 9.0# Gel based mud 7000' to 5400'.

Cement Plug 5400' to 5200' across base of point Lookout Sands.

Spot 9.0# Gel based mud 5200' to 4700'.

Spot cement 4700' to 4000'.

All cement plugs inside pipe.

PBTD 4000<sup>†</sup>

Proposed starting time July 1, 1985.