Form	9-331
(May	1963)

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Form approved.

ALTERING CASING

ABANDONMENT*

16.	Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data UBSEQUENT REPORT OF: X REPAIRING WELL
14. PERMIT	NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6485'GL	Rio Arriba New Mexico
ADDRESS PO Bo	Late managery (Show whather DE RT. CR. etc.)	Klein 9. WELL NO. 22 10. FIELD AND POOL, OR WILDCAT OTERO Chacra 11. SEC., T., R., M., OR BLK, AND SC., CR ABEA Sec., T-26-N, R-6-W NMPNI 12. COUNTY OR PARISH; 13. STATE
OH. WELL.	GAS WELL OTHER	8. FARM OR LEASE NAME
(I)o	SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	7. UNIT AGREEMENT NAME
orm 9-331 May 1963)	DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND BERIAL NO. SF 079265 6. IF INGLAN, ALBORITHM OR TRIBLE AME

(Norz: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

WATER SHUT-OFF

(Other)

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Spudded well. Drilled surface hole. 7-23-73

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Ran 4 joints 8 5/8", 24#, K-55 surface casing, 135' set at 135'GL. 7-24-73 Cemented with 106 cu.ft. cement, circulated to surface. WOC 12 hours.



8. I hereby certify that the foregoing is true and correct SIGNED	Drilling Clerk	July 25, 1973	
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	