UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry	Notices and Reports on	Wells
1. Type of Well GAS	DEC27.1991	5. Lease Number SF-078878 6. If Indian, All.or Tribe Name
2. Name of Operator Meridian Oil Inc.	OIL CON. DIV	7. Unit Agreement Name Canyon Largo Unit 8. Well Name & Number
3. Address & Phone No. of Box 4289, Farmington,		Canyon Largo Unit #247
4. Location of Well, Foot 1450'N, 820'E Sec.27,		10.Field and Pool Ballard Pic.Cliffs 11.County and State Rio Arriba County, NM
		OTICE, REPORT, OTHER DATA
Type of Submission X Notice of Intent	Abandonment	of Action <u>X</u> Change of Plans New Construction
Subsequent Report	Casing Repair	<pre>Mew Construction Non-Routine Fracturing Water Shut Off</pre>
Final Abandonment	Altering Casir Other	ng Conversion to Injection
13. Describe Proposed or	Completed Operations	
from your office to isolar sundries have been approved and for the repair of the for the csg repair, it has well. When the well was set @ 1080', and the csg	red for an additional second for an additional second leak (11-27-91). It is been found that there is suspected of a leak in the held a pressure test. It were not run to isolate well as a csg repair filed. Please disregar	In writing the procedure re is not a csg leak in the cotober 1990, a plug was The well did not have a late the leak. Engineering candidate, thus the ard the mistakenly filed
14. I hereby certify the Signed May Malfue	3 3	ue and correct y Affairs Date 12-16-91 ACCURATION FOR EXPROSE
(This space for Federal of	or State office use)	
APPROVED BY	TITLE	DEC 26 1991 DATE
CONDITION OF APPROVAL, II		SMV SMV