Form	3160-5
(June	1990)
١	

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED					
Budget Bureau No. 1	004-0135				
Expires: March 31.	. 1993				

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

	,	•	-	 42	•	_	 ,,,	511	aı	.10	,11	a	ıζα	3	CI	14	ı	1	מ
7	·	_	_	 •	٦.	-		_								_	_	_	

	•	
Jicarilla	Contract	117

SUNDRY NOTICES AND	6. If Indian. Allottee or Tribe Name			
Do not use this form for proposals to drill of				
Use "APPLICATION FOR I	PERMIT - " for such proposals	Jicarilla Apache		
SUBMIT	7. If Unit or CA, Agreement Designation			
1. Type of Well Oil X Gas Other 2. Name of Operator	DIE COLONIEL	8. Well Name and No. Jicarilla 117E 9		
Taurus Exploration, U.S.A., Inc. 3. Address and Telephone No. 2198 Bloomfield Highway; Farmington	, NM 87401 AUG 2 0 1998	9. API Well No. 30-039-21197 10. Field and Pool, or exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Des 1700' FSL, 1800' FWL, Sec. 33, T26N	Blanco Mesaverde			
	R3W, NMPM OIL CON, DIV.	11. County or Parish, State Rio Arriba NM		
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	Ne tranj		
X Notice of Intent	Abandonment	Change of Plans		
Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing		
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection		

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is intended to shut off water production from the Cliff House as follows:

- 1. MIRU. Release packer and TOH.
- 2. Set CIBP at 6100'. TIH with packer set at 5500'. Squeeze cement upper performations with 100 sks. class B cement. WOC.
- 3. TOH. TIH and drill out cement. Test casing to 500 PSI.
- 4. Clean out to 6450'. TOH.
- 5. Land tubing at 6300'. Return to production.

14. I hereby cerufy that the foregoing is true and correct Signed	Title Production Superintendent	Date 8/7/98
(This space for Federal or State offine use) Approved by Conditions of approval, if any:	Lands and Mineral Resources,	Date At 1998