Form 9-331 (May 1963) DEPA			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for projectals to drill or to deepen or plug back to a different reservoir. Cze "APPLICATION FOR PERMIT" for such proposals.)			6. IF The IAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS WELL TOTHER OTHER			7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
Northwest Production			Jicarilla 119N
P. O. Box 990, Farmington, NM 87401			9. WELL NO.
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 			Blanco Mesa Verde
1630'N, 1500'W			Sec ^{sunvey} or 1-26-N, R-4-W N.M.P.M.
14. PERMIT NO.	15. ELEVATIONS (Show whether 7198' GL	DF, RT, GR, etc.)	Rio Arriba New Mexic
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLE proposed work. If well is nent to this work.)* 06-02-76 Spudded w casing, 2	directionally drilled, give subsurface lo	water shut-off FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report re Completion of Rec tent details, and give pertinent details, and measured and true vo	REPAIRING WELL ALTERING CASING ABANDONMENT* sults of multiple completion on Well completion Report and Log form.) ates, including estimated date of starting any ertical depths for all markers and zones perti-

JUN 14 1976

OIL COLOR Clerk
Drilling Clerk
DATE

DATE

*See Instructions on Reverse Side

18. I hereby certify that the foregoing' is true and correct

(This space for Federal or State office use)

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY: