

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Supron Energy Corporation

3. ADDRESS OF OPERATOR
P.O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: **940 Ft./N; 1100 Ft./E line**
AT TOP PROD. INTERVAL: **Same as above**
AT TOTAL DEPTH: **Same as above**

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Ran 4-1/2" Casing		

5. LEASE
Contract No. 153

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla "J"

9. WELL NO.
13-E

10. FIELD OR WILDCAT NAME
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 36, T-26N, R-5W, N.M.P.M.

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6675 R.K.B.



(NOTE: Report results of multiple completion of zone change on Form 9-331-C)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Drilled 7-7/8" hole with mud to total depth of 7624 ft. R.K.B. Reached total depth on 10/31/80.
2. Ran 240 joints of 4-1/2", 10.50#, K-55 casing. Landed at 7624 ft. R.K.B. Float collar at 7589 ft. R.K.B. D.V. tools set at 5533 and 3217 ft. R.K.B.
3. Cemented first stage with 350 sacks of 50-50 poz mix with 2% gel and 10% salt. Plug down at 5:45 P.M. 11/1/80. Cemented second stage with 430 sacks of 50-50 poz mix with 2% gel and 6-1/4 lb. of Gilsonite per sack and 50 sacks of class "B" with 2% calcium chloride. Plug down at 8:45 P.M. 11/1/80. Cemented third stage with 200 sacks of Howco Lite with 12-1/2 lb. of Gilsonite per sack and 10% salt and 50 sacks of class "B" with 2% calcium chloride. Plug down at 11:45 P.M. 11/1/80.
4. Ran temperature survey and found cement top at 1000 ft. R.K.B.
Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Kenneth E. Roddy TITLE Production Supt. DATE November 3, 1980
Kenneth E. Roddy

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MGCC

AW