

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Amoco Production Company

3. ADDRESS OF OPERATOR
2325 E. 30 St., Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1740' FNL x 903' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, etc.)
7501' GR

RECEIVED

FEB 09 1987

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.
Jicarilla Apache A 118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla Apache All8

9. WELL NO.
10

10. FIELD AND POOL, OR WILDCAT
NE Ojitos Gallup Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SE/NE Sec 35, T26N, R3W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANE ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☒
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Moved in and rigged up service unit on 1-15-87. Tripped out rods and pump. Tagged and cleaned out fill. Spotted 500 gals. 15% HCL acid across Dakota perforations. Swabbed well and cleaned out casing with heated water. Set a bridgeplug at 7750'. Spotted 750 gals. 15% HCL acid across Gallup perforations. Swabbed acid back. Landed 2-7/8" tubing at 7540'. Ran pump and rods and checked pump action. Released the rig on 2-3-87.

18. I hereby certify that the foregoing is true and correct

SIGNED B. S. Shaw

TITLE Adm. Supervisor

DATE 2-5-87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

FEB 09 1987

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA