



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office .....

Lease No. ....

Unit .....

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL .....	SUBSEQUENT REPORT OF WATER SHUT-OFF .....	
NOTICE OF INTENTION TO CHANGE PLANS .....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING .....	MAR 15 1959
NOTICE OF INTENTION TO TEST WATER SHUT-OFF .....	SUBSEQUENT REPORT OF ALTERING CASING .....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL .....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR .....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE .....	SUBSEQUENT REPORT OF ABANDONMENT .....	
NOTICE OF INTENTION TO PULL OR ALTER CASING .....	SUPPLEMENTARY WELL HISTORY .....	
NOTICE OF INTENTION TO ABANDON WELL .....	Record of Sand-oil frac .....	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 13, 1959, 19...

Well No. 1 Federal is located 530 ft. from SW line and 2110 ft. from E line of sec. 35

SE 1/4 Sect. 35 (1/4 Sec. and Sec. No.) 25N (Twp.) 10W (Range) NMPM (Meridian)  
Blati (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6761 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Sand-Oil Frac Treatment

35,000 lbs. sand

33,000 gal oil

128 balls

Breakdown pressure 3,200 -1,000 psi

Close-in 2,150 -1,000 psi

Injection rate --39.2 BPM

Sand settling rate -- 16 ft./min.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wellshire Development Company

Address 425 Petroleum Club Bldg.

Denver 2, Colo.

By [Signature]  
Title Sec'y. - Treasurer