

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 079958

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Water Injection2. NAME OF OPERATOR
Skelly Oil Company3. ADDRESS OF OPERATOR
1860 Lincoln Street - Denver, Colorado 802034. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1930' FEL Section 33-25N-10W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6831' DF

7. UNIT AGREEMENT NAME
East-Bisti Unit

8. FARM OR LEASE NAME

9. WELL NO.
7810. FIELD AND POOL, OR WILDCAT
Bisti Lower Gallup11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 33-25N-10W

12. COUNTY OR PARISH
San Juan13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

All depths shown are from Ground Level.

7/30/71 - MI&RU Aztec Well Servicing Unit. No rods in hole.

Spotted cement plug from 5385' to 5285'. Pulled 2" tubing.

Worked 5 1/2" casing to free same. Rigged up Blue Jet, perforated from 1734' to 1735' w/4 shots and from 999' to 1000'. Ran 2" tubing.

Spotted cement plug from 1735' to 1585' and from 1000' to 900'. Pulled 2" tubing.

Shot casing off at 806'. Spotted cement plug from 856' to 756'.

Pulled total of 26 joints 810' of 5 1/2" casing.

Spotted 10' cement plug in surface casing. Installed dry hole marker

Completed P&A 8/6/71.



18. I hereby certify that the foregoing is true and correct

SIGNED L. L. BieleTITLE Lead ClerkDATE December 10, 1971.

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

2 Copies to N.M. O&G