horm.	2-3 1
(May	1003)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on re-

SUBMIT IN TRIPLICATE.

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND BERIAL NO.

GEOLOGICAL SURVEY

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
--------	---------	-----	---------	----	-------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

					344-			<i>!</i>
۳,	IF	INDE	AN.	ALL	OTTER	OR	TRIBE	MAMI

١.	OIL GAS			7. UNIT AGREEMENT NA		
<u>.</u>	WELL WELL OTHE	Injection Well		East Bisti		
z .	NAME OF OPERATOR		10100	8. FARM OR LEADE NAM	r	
	Skelly Oil Company		/ Was			
3.	ADDRESS OF OPERATOR		1381	9. WELL, NO.	· 	
	1860 Lincoln Stree	t, Denver, Colorado 8	0203 JUN - DOMES	62		
4.	LOCATION OF WELL (Report locati See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT				
	At surface		Oil DIST. 3	Bisti Lowe	r Gallup	
	30001 mm - 4	11. BEC., T., R., M., OR BLK. AND BURVEY OR AREA				
	1980. FNL & 66	60' FWL Section 34-25N-	-10W .			
				Section 34-	25N-10W	
14.	PERMIT NO.	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE			
		6930' DI	F	San Juan	New Mexi	
16,	Check	Appropriate Box To Indicate	Nature of Notice, Report, or C	ther Data		
		NTENTION TO:	SUBSEQUENT REPORT OF:			
	TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	TILL	
	FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	SING	
	SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	т•	
	REPAIR WELL	CHANGE PLANS	(Other)			
	(Other)			of multiple completion e etion Report and Log for		
17.	proposed work. If well is dis	orenations (Clearly state all pertine rectionally drilled, give subsurface loc	ent details, and give pertinent dates, ations and measured and true vertica	including estimated date I depths for all markers	of starting any	

This well has reached the economic limit and is no longer profitable to operate. Plans are to plug and abandon this well; plugging as follows:

First Plug - 100' plug across Gallup Zone perforations 5286-5336'Second Plug - 50' inside the 5-1/2'' casing and 50' above where casing is shot in two

Third Plug - 150' cement plug extending downward from above the Fruitland Coal section across the Pictured Cliffs Sand

Fourth Plug - 100' plug at bottom of Ojo Alamo Sand (unless surface casing is set through the Ojo Alamo Sand)

10 sacks of cement in top of surface casing with dry hole marker

8. I hereby certify that the foregoing is true and corner	TITLE District Operations Supt.	DATE June	10, 1971
(This space for Federal or State office uso)			
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	