

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 078621
2. NAME OF OPERATOR Shelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Santa Fe
3. ADDRESS OF OPERATOR 1860 Lincoln Street, Denver, Colorado 80203		7. UNIT AGREEMENT NAME East Bisti Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1600' FSL and 300' FEL Section 29-25N-10W		8. FARM OR LEASE NAME
14. PERMIT NO.		9. WELL NO. 47
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5560' GR		10. FIELD AND POOL, OR WILDCAT Bisti Lower Galloway
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 29-25N-10W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

All depths shown are from ground level.

7-13-71 - MI & RU Aztec Well Service Unit. Pulled rods.

Spotted cement plug from 5277' to 5177'. Pulled 2" tubing.

Pulled and worked 5-1/2" casing to free same. Rigged up blue jet, perforated from

1644' to 1645' w/4 shots and 879' to 880' w/4 shots. Ran 2" tubing. Spotted cement

plug from 1645' to 1495'. Pulled tubing up the hole. Spotted cement plug from

880' to 780'. Pulled tubing. Shot 5-1/2" casing at 776'. Would not come loose.

Shot 5-1/2" casing at 553'. Spotted cement plug from 603' to 593', 50' inside

casing stub and 50' above casing stub.

Pulled 14 joints 556' of 5-1/2" casing.

Spotted 10' cement plug in surface casing. Installed dry hole marker.

Completed 2 & A 7-17-71.

18. I hereby certify that the foregoing is true and correct

SIGNED

G. L. Butler

TITLE

Lead Clerk

DATE

10-10-71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side