



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. SP-078061
Unit Carson

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
<u>Notice of Conversion to Injector</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 21, 1961

Carson Unit
Well No. 11-20 is located 660 ft. from N line and 656 ft. from E line of sec. 20

11 20 25 11
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blair San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)
Blair Kelly Lushing San Juan New Mexico

The elevation of the drill floor above sea level is 6459.4 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings indicate mudding jobs, cementing points, and all other important proposed work)

1. Run T.D. 5055'; casing 8-5/8" at 104', 4-1/2" at 5054'; Perforations (1/2" holes/ft.)
2. Perforations 4906-26, 4937-48, 4979-85, 4992-5006, 5010-22.
3. Pressure test tubing with 1000 psi for 15 min.
4. Pull tubing and bail clean.
5. Run 2-3/8" open-ended tubing to bottom and swab while running clean Point Lookout water (treated with Triton X-100 detergent) down casing. When fluid cleans up, pull tubing.
6. Run 2-3/8" tubing with packer ten feet above perforations.
7. Pump 60 bbls. of inhibited water down annulus to displace uninhibited fluid. Set packer and fill with inhibited water.
8. Run pressure and temperature surveys as directed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shell Oil Company
Address Post Office Box 1200
Farmington, New Mexico

Original Signed by
W. M. MARSHALL

By _____
Title W. M. Marshall
Division Exploitation Engineer

