


(SUBMIT IN TRIPLICATE)

Land Office San Juan Co  
Lease No. 078193  
Unit San. 2130

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 29, 1957

Well No. 2 is located 660 ft. from S line and 660 ft. from W line of sec. 15


C-21, 22 Section 15 (1/4 Sec. and Sec. No.)  
25N (Twp.) 13W (Range) New Mexico P.M. (Meridian)  
San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ground level above sea level is 6394 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 4971' HD. Completed logs, run drill pipe open ended, special heavy and from 4971' to 4800'; 45 run cement from 4800' to 4600'; heavy and from 4600' to 3900'; 45 run cement from 3900' to 3700'; heavy and from 3700' to 1200'; 45 run cement from 1200' to 1000'; heavy and from 1000' to 20'; 10 run cement in top of casing. Special marker, filled collar with soil and standard locational



I understand that this plan of work must receive approval in writing by the Geological Survey before work may be commenced

Company THE BRITISH-AMERICAN OIL PRODUCING COMPANY  
Address BOX 100  
BOULDER 1,  
COLORADO

Original Signed By: J. E. Stein  
By \_\_\_\_\_  
Title District Engineer

*[The page contains extremely faint and illegible text, likely bleed-through from the reverse side of the document. The text is scattered across the page and does not form any recognizable words or sentences.]*