Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter all abandoned well. Use Form 3160-3 (APD) for such proposals

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

NMNM-036253

5. If Indian, Allottee or Tribe Name

abandoned Well.					
SUBMIT IN TRIPL	CATE - Other instr	ca actions on revers	e side	7. If Unit or C	A/Agreement, Name and/or No.
1. Type of Well X Oil Well Gas Well 2. Name of Operator Elm Ridge Resources, Inc.	8. Well Name and No. E.W. Mudge #6 9. API Well No. 30-045-05350				
3a. Address PO Box 189 Farmington, NM 8	3b. Phone No. (include 505-632-3476	area coae)	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R. 660' FSL & 1980' FEL Sec. 16-T25N-R11W	, M., or Survey Description)			Bisti Lower Gallup 11. County or Parish, State San Juan, New Mexico	
12. CHECK APPROPRIATE BOX(E	S) TO INDICATE NATURE	OF NOTICE, REPORT	, OR OTHER DA	TA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Reclamation	Start/Resume)	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily		Other
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispo		
13. Describe Proposed or Completed Operation If the proposal is to deepen directionally Attach the Bond under which the work Following completion of the involved operation.	or recomplete horizontally, give will be performed or provide the grations. If the operation results in	subsurface locations and mea	sured and true vertice 1/BIA. Required subsecompletion in a new	at depuns of all posequent reports show interval, a Form	all be filed within 30 days 3160-4 shall be filed once

Elm Ridge Resources, Inc proposes to plug and abandon the E.W. Mudge #6 in accordance with regulations. Production equipment will be removed from the well and tubing will be used to pump plugs. Perforate and squeeze will be used unless casing can be recovered over the specified interval. Proposed procedure: Notify the BLM office 24-hours prior to commencement of plugging procedure. Set a CIBP @ 4720'. Set a 50' cement plug from 4670' to 4720' across Gallup top of 4720'. Set a 100' cement plug from 1955' to 2055' across top of Mesa Verde top of 2005' inside and outside 4-1/2 casing. Set a 230' cement plug from 1140' to 1370' across top of PC/FC PC top @ 1320' FC @ 1190' inside and outside of 4-1/2 casing. Set a cement plug from surface to 361' across top of Ojo Alamo top @ 311' inside and outside of 4-1/2 casing. Cut off wellhead. Install dryhole markers. Clean and remediate location.

Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

Certified return receipt # 7001 0320 0002 6707 1880

Certified rotal	ii roooipt ii	7001 0020 0002							
14. I hereby certify	y that the forego	ing is true and correct							
Name (Printed/Typed) Trudy Grybelnik					Title	Production Technician			
Signature	Mude	1 Dun	ah.	\bigcup	Date	March 20, 2002			
			THIS S	PACE FOR	FEDERAL O	R STATE USE			
Approved by	4.2	1			Title	PE	Date 4/(1/0L		
certify that the appli	icant holds legal	ttached. Approval of to or equitable title to the conduct operations the	ose nghts m	the subject	int or Office lease	FFO			
William World China							Cat - TT-id-d Ctates any folio fictitions or		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Testing has been completed.

determined that the site is ready for final inspection.)