

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Water Source

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P.O. Box EE, Cortez, Colorado 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

14. PERMIT NO. 660' N of S line; 660' E of W line

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6455 DF

5. LEASE DESIGNATION AND SERIAL NO.
14-20-603-1431

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Allottees

7. UNIT AGREEMENT NAME
Northeast Bisti Unit

8. FARM OR LEASE NAME
Northeast Bisti Unit

9. WELL NO.
4

10. FIELD AND POOL, OR WILDCAT
Bisti Lower Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 14, T25N, R11W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon this well because it is no longer of any economical value. The water flood, for which it was the source well is uneconomical and has been abandoned. There are no other pay prospectives in this well. Cumulative production from the lower Gallup was 528 bbls. oil. The water produced from the Mesa Verde is blackish and unsuitable for stock.

ABANDONMENT PROCEEDURE:

Pull rods and tubing. Run tubing open ended and mud up. Spot 75sx. cement from 2550' to 2000', pull tubing. Determine casing free point, cut and pull. Run tubing, spot 40sx. 50' below and above casing stub. Spot 145sx. 560' to 235' covering the Ojo Alamo and 50' into the surface pipe. Place marker in 10sx. surface plug and clean location.



18. I hereby certify that the foregoing is true and correct

SIGNED Alvin R. Mann

TITLE Field Foreman

DATE 10-24-73

(This space for Federal or State office use)

APPROVED BY M

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: