orm 9-331 (May 1963)

FRACTURE TREAT

SHOOT OR ACCURE

REPAIR WELL

UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBMIT IN TRIPLICATE.

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

ALTERING CASING

ABANDONMENT*

E. W. Mudge No. 3 GEOLOGICAL SURVEY SF 078064 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL WELL Salt Water Source OTHER Carson Unit 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Shell Oil Company Lialia Dource 3. ADDRESS OF GPERATOR 6-1/3 1700 Broadway, Denver, Colorado 80290 LOCATION OF VILL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT At surface Bisti 11. sec., t., e., m., or elk. and survey or area Section 13-T25N-R12W 724' FNL & 2640' FEL Section 13 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 14, PERMIT NO. San Juan 6380 KB N.M. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

See attachment

MAR 1 9 1984

OIL CON. DIV.
DIST. 3

WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct	TITLE	Div. Opers. Engr. DATE 9/27/77
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	metallist.
cc: NMO&GCC	•	Austra Literarischer

*See Instructions on Reverse Side

NMOCTO

BISTI

D ABANDON

LEASE CARSON UNIT WELL NO. 6-13 WSW

DIVISION WESTERN ELEV 6380 KB

COUNTY SAN JUAN STATE NEW MEXICO

NEW MEXICO | BISTI FIELD | Carson Unit 6-13 WSW

(P&A)

"FR" TD 3805. PB 3789. AFE #570026 provides funds to plug & abandon well. 9/20 RU Bedford & pulled 1" & 7/8" rods. SEP 2 2 1977

Carson Unit 6-13 WSW (P&A)

TD 3805. PB 3789. No report.

SEP 2 3 1977

Carson Unit 6-13 WSW (P&A)

TD 3805. PB 3789. No report. SEP 2 6 1977

Carson Unit 6-13 WSW (P&A)

TD 3805. PB 3789. 9/21 Pulled 30 jts tbg; pull'g 30,000# over tbg wt. Tbg stuck 30 jts out of hole. 9/22 Ran 30 jts tbg back in hole. Cut tbg above seat'g nip & anchor; tbg still tight. 9/23 Spt'd 200 sx cmt plug thru stuck tbg over Allison Menefee perfs. 9/24 Perf'd tbg & csg @ 1200'. Spt'd 100 sx cmt; sqz'd 40 sx. Perf'd tbg & csg @ 400'. Spt'd 60 sx cmt; sqz'd 35 sx. Backed tbg off; got 10 jts. Pulled 10 jts & placed 10 sx cmt plug on sfc. Set abandonment marker & RD Bedford. SEP 2 7 1977 FINAL REPORT

