

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
E. W. Mudge No. 3
SF 078064
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 41-13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 660' FEL Section 13	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6380' KB
	12. COUNTY OR PARISH San Juan
	13. STATE N. Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) _____

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED <u>L. P. Plautz</u>	TITLE <u>Div. Opers. Engr.</u>	DATE <u>JUL 29 1977</u>
(This space for Federal or State office use)		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

cc: New Mexico O&GCC w/attachment

*See Instructions on Reverse Side

PLUG AND ABANDON WELL

SHELL OIL COMPANY

FROM: 6/21-27/77

LEASE CARSON UNIT

DIVISION WESTERN

COUNTY SAN JUAN

WELL NO.

ELEV

STATE

BISTI

41-13

6380 KB

NEW MEXICO

NEW MEXICO

BISTI FIELD

Carson Unit 41-13
(P&A)

"FR" TD 5050. WO #528926 provides funds to plug and abandon well. 6/20 RU Bedford. Ran tbg workstring to TD & SD.

JUN 21 1977

Carson Unit 41-13
(P&A)

TD 5050. Loaded hole w/mud. Spt'd 20 sx cmt plug over & above perfs. Pulled & LD tbg. RU hyd jacks.

JUN 22 1977

Carson Unit 41-13
(P&A)

TD 5050. SD.

JUN 23 1977

Carson Unit 41-13
(P&A)

TD 5050. Shot off csg @ 1222' & spt'd 50 sx cmt plug @ csg stub. Pulled csg 430' & spt'd 60 sx cmt plug @ base of 8-5/8". Fin'd pull'g csg. RD Bedford 6/23/77.

JUN 24 1977

Unit 41-13
(P&A)

TD 5050. Installed abandonment marker 6/24/77.
FINAL REPORT

JUN 27 1977