		<i></i>
orm 3160-5		FORM APPROVED
une (990)	And the property of the contract of the contra	Budget Bureau No. 1004-0135
	的复数加州的南洋区 ,加州省第1960年中华州州	Expires: March 31, 1993
UNI	PED STATES	5. Lease Designation and Serial No.
	TOF THE INTERIOR,	SF-070322A
	LAND MAN AUCHTENT 18	6. If Indian, Allottee or Tribe Name
	AND REPORTS CANVELLS 5	
Do not use this form for proposal to	irill or to deepen or repairs to a difference eservoir.	7. If Unit or CA. Agreement Designation
-Use "APPLICATION F	FOR PERMIT—" for see proposition	A l
	DINTRIPLICATE SECTION	Central Bisti Unit
	G OLOS VED	8. Well Name and No.
. Type of Well X Oil Well G	as Well Other C DIST DIN	,37
Name of Operator	25 // 3 · · · · · · · · · · · · · · · · ·	7 9. API Well No.
•		,30-045-05461
Central Resources, Inc.	IM Riege Consignition	10. Field and Pool, or Exploratory Area
. Address and Telephone No.	27.112 (505) (22.2476	•
	New Mexico 87413 (505)-632-3476	Bisti Lower Gallup
. Location of Well (Footage, Sec., T., R		11. County or Parish, State
660' FSL, 660' FWL, Sec 10	, T25N, R12W	San Juan, New Mexico
	s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTI	
	X Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
X Final Abandonment Notice	Other	Dispose Water
	Other	(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
3 Describe Proposed or Completed Operat	lions (Clearly state all pertinent dates, including estimat	
directionally drilled, give subsurface loc	ations and measured and true vertical depths for all man	kers and zones pertinent to this work.)*
	to plug the well in accordance with regulation	
	ed. Perforate and squeeze will be used unless of	
		casing can be recovered over the specified into
there is evidence cement is in p	lace behind the casing.	
Proposed Procedure:		
A Notify the Farmington	BLM office at 505-599-8907 24 hours prior to	commencement of plugging operations.
B. Pull all retreivable down	nhole production equipment.	
C. Set a CIBP at 4770 and	spot cement on top to 4568' to 4618'	
D. Set a 100' cement plug f	from 1972' to 2072' across Menefee top at 202	2' inside and outside 5 1/2" casing
E. Set a 100' cement plug	from 1036' to 1136' across Pictured Cliffs at 1	086' inside and outside 5 1/2"casing.
E. Set a 100 cement plug s	from 810' to 710' across the Fruitland Coal at	760' inside and outside 5 1/2 " casing
F. Set a 100' cement plug	from 810 to 710 across the Fruitiana Coarac	ive shape at 227! incide and outside 5 1/2" easi
	surface to 177' to 277' across the surface cas	
H. Cut wellhead and instal	Il dry hole marker. Clear and remediate locati	on.
D. CIGI	Title Production Tech.	Date January 23, 2001
1 ath JKAD	The Hoddenon reen.	- Date Juliany 23, 2001
14. The Patty Shelton		
Si (This space for Federal or State of	fice use)	3/1/
	Title	Date 3/1/01
Conditions of approval, if any:		
Approved by		

Title 18 U.S.C. Section 1001, makes it a crime for a *See Instruction on Reverse Side fictitious or fraudulent statements or representations as to any manner within its jurisdiction.