

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,  
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.  
SF-070322

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Carson Unit

8. Well Name and No.

AB-10 44-10

9. API Well No.

30-045-05463

10. Field and Pool, or Exploratory Area

Bisti Lower Gallup

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Central Resources, Inc. intends to plug the well in accordance with regulations. Production equipment will be removed and well will be plugged as specified. Perforate and squeeze will be used unless casing can be recovered over the specified interval where there is evidence cement is in place behind the casing.

Proposed Procedure:

- Notify the Farmington BLM office at 505-599-8907 24 hours prior to commencement of plugging operations.
- Pull all retrievable downhole production equipment.
- Set a CIBP at 4740 and spot cement on top to 4942' to 4992' 4538' 1035'
- Set a 100' cement plug from 1886' to 1986' across Monofee top at 1930' inside and outside 4 1/2" casing
- Set a 100' cement plug from 1017' to 1117' across Pictured Cliffs at 1067' inside and outside 4 1/2" casing.
- Set a 100' cement plug from 795' to 695' across the Fruitland Coal at 745' inside and outside 4 1/2" casing.
- Set a cement plug from surface ~~1000'~~ to 137' across the surface casing shoe at 89' inside and outside 4 1/2" casing.
- Cut wellhead and install dry hole marker. Clear and remediate location.

Patty Shelton

Title Production Technician

Date

January 23, 2001


14. I, Patty Shelton

Si (This space for Federal or State office use)

Title

Conditions of approval, if any:

Approved by



2/27/01