UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	20 20 21 32	5.	Lease Number
1. Туј	pe of Well	6.	NM-04224 If Indian, All. or
	GAS JAN 2000 JAN ENVEN		Tribe Name
2. Na	me of Operator SURLINGTON RESOURCES OUT F CAS COMPANY	H 7.	Unit Agreement Name
	RESOURCES OIL & GAS COMPANY	7	
3. Ad	dress & Phone No. of Operator	8.	Well Name & Number Quitzau #10
	O Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No. 30045054670 0
	cation of Well, Footage, Sec., T, R, M 0' FSL, 1189' FEL Sec. 10, T-25-N, R-08-W, NMPM	10.	Field and Pool Ballard PC
	· · · · · · · · · · · · · · · · · · ·	11.	County and State San Juan Co, NM
12. C	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT	, OTHER	DATA
ту	rpe of Submission Type of Action	o of Di	- n a
		e of Pl Construc	
			Fracturing
		Shut o	
	Final Abandonment Altering Casing Conve	ersion t	o Injection
	<u>X</u> Other - Restimulation		
13.	Describe Proposed or Completed Operations		
	1. Pull 1" tubing.		
	2. Clean out (drill out) from 2,304' - 2,440'.		
	3. Run OH log. 4. Run 2-7/8" casing to new TD and cement to surface w	/ 444 7	cu ft of cement
	4. Run 2-7/8" casing to new TD and cement to surface w, Lead: 197 sks Class "B/G" w/ 2% sodium metasilicate		
	1/2 pps cellophane. Tail: 25 sks Class "B/G" w/ 1% s		
	5 pps gilsonite, 1/4 pps cellophane.		
	5 pps gilsonite, 1/4 pps cellophane. 5. Selectively perforate, acidize, and foam fracture P	ictured	Cliffs formation.
	5 pps gilsonite, 1/4 pps cellophane.5. Selectively perforate, acidize, and foam fracture P:6. Clean out well.	ictured	Cliffs formation.
	5 pps gilsonite, 1/4 pps cellophane. 5. Selectively perforate, acidize, and foam fracture P	ictured	Cliffs formation.
	5 pps gilsonite, 1/4 pps cellophane.5. Selectively perforate, acidize, and foam fracture P:6. Clean out well.	ictured	Cliffs formation.
	5 pps gilsonite, 1/4 pps cellophane.5. Selectively perforate, acidize, and foam fracture P:6. Clean out well.	ictured	Cliffs formation.
14.	5 pps gilsonite, 1/4 pps cellophane.5. Selectively perforate, acidize, and foam fracture P:6. Clean out well.		Cliffs formation.
14. Sign	5 pps gilsonite, 1/4 pps cellophane. 5. Selectively perforate, acidize, and foam fracture P: 6. Clean out well. 7. Return well to production. I hereby certify that the foregoing is true and correct	•	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Quitzau #10

Section 10 P, T-25 -N R-08 -W San Juan, New Mexico

Ballard Pictured Cliffs Field Wellbore Schematic

