UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RECEIVED

	BLM	
Sundry Notic	ces and Reports on Wells 2: 15	
. Type of Well GAS	070 FARMINGTON, NM	5. Lease Number NM-04224 6. If Indian, All. or Tribe Name
		7. Unit Agreement Name
2. Name of Operator		
BURLINGTON RESOURCES OIL &	GAS COMPANY JEGEN	8. Well Name & Number
3. Address & Phone No. of Operato		1993 - Quitzau #6
PO Box 4289, Farmington, NM		9. API Well No. [b] [V] 80-045-05505 [10. Field and Pool
4. Location of Well, Footage, Sec 807'FNL 670'FEL, Sec.10, T-25	10.00F	Ballard Pictured Clif 11. County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO IND	CATE NATURE OF NOTICE, REPORT, C	OTHER DATA
Type of Submission	Type of Action	
X Notice of Intent	Abandonment Change c	
Subsequent Report	Recompletion New Consumplier Plugging Back Non-Rout Casing Repair Water Sh	ine Fracturing
Final Abandonment	Altering Casing Conversi	
13. Describe Proposed or Comple	eted Operations	
It is intended to restimularing the following ma	ate the Pictured Cliffs formation	n of the subject well
2 7/8" casing to ne Lead: Class "B" or Celloflake. Tail: w Gilsonite, 0.25 pps	ll open hole from 2369'-2445'. R w total depth and cement to surf "G" cement with 2% Econolite, 5 ith class "B" or "G" cement with Celloflake. Perforate, acidize, mation. Cleanout. Rerun tubing,	ace with 157sx(298 cu.ft.). pps Gilsonite, 0.25 pps 1% Econolite, 5 pps & foam fracture
signed Stay Stadhild	Foregoing is true and correct. (MDW) Title Regulatory Administration (MDW)	TLW OFC 18 1998
$\langle \langle \langle \langle \langle \langle \langle \langle \rangle \rangle \rangle \rangle \rangle \rangle \rangle \rangle$	(MDW) Title <u>Regulatory Administr</u>	TLW OFC 18 1998

(8)