

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,
Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Injection Well

2. Name of Operator
Giant Exploration & Production Company

3. Address and Telephone No.
P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660' FSL, 660' FWL, Sec. 5, T25N, R12W

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

14-20-603-1292

6. If Indian, Allottee or Tribe Name

Navajo Allotted

7. If Unit or CA. Agreement Designation

Central Bisti Unit

8. Well Name and No.

Central Bisti Unit #WI-56

9. API Well No.

30-045-05525

10. Field and Pool, or Exploratory Area

Bisti Lower Gallup

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Return to Production

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Giant Exploration & Production Company intends to return the subject well to production as follows:

- 1) Clean out well to 4996'.
- 2) Pressure test casing.
- 3) Perforate Gallup (4968'-4996') w/4 JSPF.
- 4) Acidize perforations with 1000 gal. 15% HCl.
- 5) Frac tubing w/27,200 gal. cross linked gel carrying 75,000# 12/20 mesh sand.
- 6) Clean out to PBD.
- 7) Install production tubing string. (Note: if casing leaks are encountered, a scab liner with isolation packers will be run across the leaking interval prior to running the production string.)
- 8) Return well to production.

RECEIVED
DEC 15 1994
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed

Jeffrey R. Vaughan

Title Vice President Operations

Date

DEC 02 1994

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

APPROVED

DEC 06 1994

Signed: STEPHEN MASON
BUREAU OF LAND MANAGEMENT