DEPARTMENT BUREAU OF L. SUNDRY NOTICES		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. 14-20-603-1423 26.40 Indian, Allottee or Tribe Name
Do not use this form for proposals to directly a Particle of the Control of the C	lllor to deepen or reently to a different reservoir, R.PERMIT—"for such proposals	7. If Unit or CA. Agreement Designation
SUBMIT IN TRIPLICATE		Central Bisti Unit
1. Type of Well X Oil Well Gas We		8. Well Name and No. 59
2. Name of Operator		9. API Well No.
Central Resources, Inc. for Giant Exploration & Production Company		30-045-05530
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area
P.O. Box 1213, Bloomfield, New Mexico 87413 (505)632-3476		Bisti Lower Gallup
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
660' FSL, 660' FWL, Sec. 3, T2:	5N, R12W	San Juan, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION		
	X Abandonment	Change of Plans
Notice of Intent	Recompletion 1112/3	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	ater Shut-Off
	Altering Quaing	nversion to Injection
X Final Abandonment Notice	Other Control Other	Drspose Water
		Note: Report results of multiple completion on Well
13 Describe Proposed or Completed Operations	(Clearly state all martinest descriptions as in stand to	suppletion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)*		
		and zones pertinent to ans work.)
Fohmow 9 12 2001	The same of the	
February 8-12, 2001		
A. Set a CIBP at 4780' and spot cement on top using 20 sacks cement.		
B. Bring top of Gallup plug from 4580 inside outside 5 1/2" casing using 20 sacks cement.		
C. Set Mesa Verde plug from 1912' to 1812' inside and outside 5 1/2" casing using 20 sacks cement.		
D. Set the Pictured Cliffs Plug from 1182' to 1082' inside and outside 5 1/2" casing using 47 sacks cement.		
E. Set the Fruitland Coal plug from 831' to 731' inside and outside 5 1/2" casing using 47 sacks cement.		
G. Place the surface plug at 343' to surface inside and outside the 5 1/2" casing to surface using 150sacks cemen		
cover the Ojo Alamo interval.		
H. Cut well head and install dry hole marker. Clear and remediate location.		
11. Cut wen head and histain dry note marker. Clear and remediate location.		
14. I hereby certify that the foregoing is true		
Signed Att Shorton	Title Production Technician	Date February 27, 2001
Patty Shelton		
(This space for Federal or State office u	ise)	
Approved by	Title	Date
Conditions of approval, if any:		TOPPTED FOR RECORI

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agence of the wnice of the wind of