Form 3160-5 (June 1990)

Conditions of approval, if any:

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No. SF 078056

SUNDRY NOTICES AND REPORTS ON WELLS		o. If fildian, Anottee of Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		7. If Unit or CA. Agreement Designation
Use "APPLICATION FOR PERMIT" for such proposals		The same of San Agreement Designation
SUBMIT IN TRIPLICATE		Central Bisti Unit
	as Well X Other Water Injection Well	8. Well Name and No. Central Bisti Unit 6
2. Name of Operator 9. API Well No.		
Central Resources, Inc. for Giant Exploration & Production Company		30-045-055 <b>ø</b> 40
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area
P.O. Box 1213, Bloomfield, New Mexico 87413 (505)632-3476		Bisti Lower Gallup
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
1980' FSL, 1980' FWL, Sec. 6, T25N, R12W		San Juan New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
	X Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
X Final Abandonment Notice	Other	Dispose Water
		Note: Report results of multiple completion on Well
12 Decembe Promond of Co. 1 1 10		amplation Description
13. Describe Proposed of Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed by the control of the co		
directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
January 10-12th.		
A. Set a CIBP at 4758' and spot cement on top to 4658' using 30 sacks cement.		
B. Bring top of Gallup plug from 4770' to 4532' inside outside 5 1/2" casing using 30 sacks cement.		
C. Set Mesa Verde plug from 1960' to 1927' inside and outside 5 1/2" casing using 47 sacks cement.		
D. Set the Pictured Cliffs Plug from 1235' to 1183' inside and outside 5 1/2" casing using 47 sacks cement.		
E. Set the Fruitland Coal plug from 924' to 874' inside and outside 5 1/2" casing using 47 sacks cement.		
1 1/2 CASING USING 4 / CACKE CAMENT		
F. Place the surface casing shoe plug at 400' inside and outside 5 1/2" casing using 47 sacks cement.		
G. Place the surface plug at 242' to surface inside and outside the 5 1/2" casing using 100 sacks cement to		
cover the Ojo Alamo interval.		
H. Cut well head and install dry hole marker. Clear and remediate location.		
14. I hereby certify that the foregoing is	true and correct	
Signed Signed	mit D 1 il m	Data 01/15/2001
Patty Shelton	S. The Frederick Feelincian	Date 01/15/2001
(This space for Federal or State offi	Ce lice)	
Approved by	Tr'. I	)ota

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction. AHIM urrick

Date