

6mndef

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
SF 078056

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Central Bisti Unit

8. Well Name and No.
Central Bisti Unit 6

9. API Well No.
30-045-055040

10. Field and Pool, or Exploratory Area
Bisti Lower Gallup

11. County or Parish, State
San Juan, New Mexico

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Water Injection Well

2. Name of Operator
Central Resources, Inc. for Giant Exploration & Production Company

3. Address and Telephone No.
P.O. Box 1213, Bloomfield, New Mexico 87413 (505)632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FSL, 1980' FWL, Sec. 6, T25N, R12W

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

January 10-12th.

- A. Set a CIBP at 4758' and spot cement on top to 4658' using 30 sacks cement. DID NOT HOLD. Tagged at 4770
- B. Bring top of Gallup plug from 4770' to 4532' inside outside 5 1/2" casing using 30 sacks cement.
- C. Set Mesa Verde plug from 1960' to 1860' inside and outside 5 1/2" casing using 47 sacks cement.
- D. Set the Pictured Cliffs Plug from 1235' to 1135' inside and outside 5 1/2" casing using 47 sacks cement.
- E. Set the Fruitland Coal plug from 924' to 824' inside and outside 5 1/2" casing using 47 sacks cement.
- G. Place the surface plug at 242' to surface inside and outside the 5 1/2" casing to surface using 100 sacks cement cover the Ojo Alamo interval.
- H. Cut well head and install dry hole marker. Clear and remediate location.

14. I hereby certify that the foregoing is true and correct

Signed Patty Shelton
Patty Shelton

Title Production Technician

Date 01/15/2001

(This space for Federal or State office use)

Approved by _____

Title _____

Date _____

Conditions of approval, if any:

ACCEPTED FOR RECORD