



FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.
14-20-603-323

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Central Bisti Unit

8. Well Name and No.
99. API Well No.
30-045-0554110. Field and Pool, or Exploratory Area
Bisti Lower Gallup11. County or Parish, State
San Juan, New Mexico

1. Type of Well

☒ Oil Well☐ Gas Well ☐ Other

2. Name of Operator

Central Resources, Inc.

Elm Ridge

3. Address and Telephone No.

P.O. Box 1213, Bloomfield, New Mexico 87413 (505)-632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL, 660' FEL, Sec 5, T25N, R12W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☒

Abandonment

☐

Recompletion

☐

Plugging Back

☐

Casing Repair

☐

Altering Casing

☐

Other

☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Central Resources, Inc. intends to plug the well in accordance with regulations. Production equipment will be removed and well will be plugged as specified. Perforate and squeeze will be used unless casing can be recovered over the specified interval where there is evidence cement is in place behind the casing.

Proposed Procedure:

A.. Notify the Farmington BLM office at 505-599-8907 24 hours prior to commencement of plugging operations.

B. Pull all retrievable downhole production equipment.

C. Set a CIBP at 4966' and spot cement on top to 4916' to 5016'

D. Set a 100' cement plug from 2945' to 3945' across Menefee top at 2995' inside and outside 5 1/2" casing

E. Set a 100' cement plug from 1064' to 1164' across Pictured Cliffs at 1110' inside and outside 5 1/2" casing.

F. Set a 100' cement plug from 704' to 804' across the Fruitland Coal at 750' inside and outside 5 1/2" casing.

G. Set a cement plug from surface to 248' to 348' across the surface casing shoe at 298' inside and outside 5 1/2" casing.

H. Cut wellhead and install dry hole marker. Clear and remediate location.

14. I, the Patty SheltonTitle Production Tech.

Date

February 14, 2001

Si (This space for Federal or State office use)

Title

Date

3/16/01

Conditions of approval, if any:

Approved by

Title 18 U.S.C. Section 1001, makes it a crime for a fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

NMOC