

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
14-20-603-321

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Central Bisti Unit

8. Well Name and No.
10

9. API Well No.
30-045-05543

10. Field and Pool, or Exploratory Area
Bisti Lower Gallup

11. County or Parish, State
San Juan County, New Mexico

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Central Resources, Inc.

3. Address and Telephone No.

P.O. Box 1247, Bloomfield, New Mexico 87413 (505) 932-3333

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL, 1880' FWL, Sec 4, T25N, R12W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☒ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Central Resources, Inc. intends to return the well to production by testing with packer and bridge plug to find the casing leak. Depending on the location of the leak, the casing will be removed and replaced by tieback operations with cement to surface or the leak will be squeeze cemented until integrity is returned to the system. After casing integrity has been re-established, the well will be returned to production. The well will be tested and a current well test submitted to the BLM for record.

The work required to repair the well will be reported to the BLM in detail.

The Farmington BLM office at 505-599-8907 24 hours prior to commencement of any cementing operations.

You will also be given notice and opportunity to witness the well test after the well is returned to production.

Please allow until December 31, 2000 to complete the return to production operations.

14. I hereby certify that the foregoing is true and correct

Signed Rodney L. Seale
Rodney L. Seale

Title District Manager

Date April 24, 2000

(This space for Federal or State office use)

Approved by Charlie Beecham

Title Team Lead, Petroleum Management

Date MAY - 1 2000

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

CENTRAL RESOURCES, INC.

Central Bisti Unit No. 10

Review Date: 4-15-00 by Rod Seale

Elevation: 6133' GL, 6144' KB


Location: 1980' FSL, 1880' FWL, Sec 4, 25-N, 12-W, San Juan County, New Mexico


Field: Bisti Lower Gallup

Zone: Lower Gallup

Perfs: 4755' - 4932'

Spud Date: May 19, 1958 12:00 AM




Rod Seale, Printed on 4/24/00