

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR MARTIN Oil & Gas Co.	8. FARM OR LEASE NAME MCKEE
3. ADDRESS OF OPERATOR 4705 North 32 <sup>ND</sup> Place PHOENIX, ARIZONA	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 800' fNL 990' fWL Sec 1, T25N R11W SAN JUAN Co. New Mexico	10. FIELD AND POOL, OR WILDCAT WILDCAT
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6445 DF
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 1 T25N R11W NMPM
	12. COUNTY OR PARISH SAN JUAN
	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well has been plugged & ABANDONED as follows:

11-1-67 move in equipment  
11-2-67 Squeeze perfs 5232 to 5418 w/25sx  
11-3-67 Cut 5 1/2" casing off @ 2249  
Spot 50sx plug from 2400 to 2200  
11-4-67 Spot 38sx plug from 1550-1650  
Erect P&A marker w/ 10sx surface plug  
11-5-67 Rig down, Clean Loc.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AGENT for Operator

DATE

11-10-67



(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side



U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.