

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>		7. UNIT AGREEMENT NAME Huerfano Unit	
2. NAME OF OPERATOR El Paso Natural Gas Company		8. FARM OR LEASE NAME Huerfano Unit	
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499		9. WELL NO. 154	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790'N, 1650'W		10. FIELD AND POOL, OR WILDCAT Undes. Pic. Cliffs	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6786' GL	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PELL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

REVISED REPORT

04-06-88 MOL&RU. NU BOP. Released pkr. TOO H w/pkr. TIH w/work string. Spot 120 sx. Class "B" plug 2233-1760'. TOO H. SDFN.
04-07-88 TIH w/tbg. Tag top of cmt. @ 1764'. Circ hole w/9.2# mud. TOO H. Perf 4 squeeze holes @ 1330'. Ran tbg. to 1330'. Spot 80 sx Class "B" cmt @ 1330'. Squeezed 25 sx. into perfs & left 55 sx. in pipe. Top of cement in pipe @ 1044'. TOO H, lay down tbg. Ran wireline to 150'. Perf 4 holes @ 150'. Circ. cmt. to surface. Set dry hole marker w/10 sx. Released rig.

Approved as to completion of work and
Liability under Federal law, provided the
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Clerk()

DATE

04-09-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

APR 15 1988

AREA MANAGER

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC