

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Bureau No. 49-11424

5. LEASE DESIGNATION AND SERIAL NO.

NMA 036254

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

Central Bisti Unit

8. FARM OR LEASE NAME

CBU

9. WELL NO.

WI #7

10. FIELD AND POOL, OR WILDCAT

Bisti Gallup

11. SECTION, TOWNSHIP, OR RANGE

Sec 15, T25N, R12W
NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

1. OIL
WELL ☐ GAS
WELL ☐ OTHER

Water Inj Well

2. NAME OF OPERATOR

Hixon Development Co

3. ADDRESS OF OPERATOR

341 Milam Building San Antonio, Tx

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface1315' FNL & 1315' FNL Sec. 15
T25N, R12W San Juan Co N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

6268 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

This well is no longer necessary for operation
of unit. It is intended to plug & abandon this
well in the following manner.

1. Squeeze Perfs. #754-4877
2. Spot 10 sq plug across top of Pt. Lookout
inside 4 1/2" Csg.
3. Cut & Pull 4 1/2" Csg.
4. Spot plug 50' in & 50' out of Stub.
5. Spot 150 ft plug over PC.
6. Set P&A marker w/ 10 sq Surface
7. Clean Loc.



18. I hereby certify that the foregoing is true and correct

SIGNED Larry G. Bedford TITLE Agent for OperatorDATE July 1, 1974

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

