						1	
Form 9-331 (May 1963)					Form approved Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION/AND SERIAL NO. SF 078020		
(Do not use	JNDRY NC this form for pro Use "APPL	OTICES AND REPC	ORTS ON or plug back for such propo	WELLS to a different reservoir.	6. IF INDIAN, ALLOT	TEE OR TRIBE NAME	
OIL GAS WELL OTHER  2. NAME OF OPERATOR					Huerfano (	7. UNIT AGREEMENT NAME HUETSANO Unit 8. FARM OR LEASE NAME	
El Paso Na 3. Address of open P. O. Box	ATOR	Huerfano U 9. WELL NO. 190					
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  1025'N, 1840'E					Basin Dakota  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T25N, R10W		
14. PERMIT NO.		15. ELEVATIONS (Show v	whether DF, RT,	GR, etc.)	12. COUNTY OR PART	New Mexico	
16.	Check		dicate Nati	ure of Notice, Report, or	Other Data		
SHOOT OR ACIDE REPAIR WELL (Other)  17. DESCRIBE PROPOS proposed worl	TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  ABANDON*  CHANGE PLANS			Completion or Recor	esults of multiple completion on Well completion Report and Log form.)		
Set produc	tion packe	r at 6596'.					
					MAY 7 19	75	
					•		