

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME Huerfano Unit
2. NAME OF OPERATOR El Paso Natural Gas Company	8. FARM OR LEASE NAME Huerfano Unit
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	9. WELL NO. 199
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1750'S, 990'W	10. FIELD AND POOL, OR WILDCAT Undes. Greenhorn
14. PERMIT NO.	11. SEC., T. R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-25-N, R- 9-W N.M.P.M.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6727' GL	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

POLL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

A decision has been made to plug & abandon this well by August 1, 1988, using the following procedure:

Circulate hole w/9.2# mud. Spot 17 sx (20 cu.ft.) of Class "B" neat cement from 6479-6311', covering Greenhorn perms. WOC & tag plug. Displace hole w/9.2# mud and spot 8 sx (9.3 cu.ft.) Class "B" neat cement 5526-5426' across Gallup. Displace hole w/9.2# mud. Perforate noles @ 3565' and 228'. Set retainer @ 3465', est. rate into perms & squeeze 28 sx (32.7 cu.ft.) Class "B" neat cement to cover Mesa Verde (3565-3465'). Displace hole w/9.2# mud. Spot 11 sx (13 cu.ft. of Class "B" neat cement 2036-1905' across Fruitland/Pictured Cliffs tops. Displace hole w/mud. Spot 18 sx (21.2 cu.ft.) Class "B" neat cement 1344-1116' across Kirtland/Ojo Alamo tops. Displace hole w/9.2# mud. Circulate 75 sx (88 cu.ft.) Class "B" neat cement to surface. Cut off wellhead and set dry hole marker

RECEIVED
FEB 16 1988

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling Clerk

CON. DIV.
DIST. 3
APPROVED 04-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

FEB 16 1988

AS AMENDED

AREA MANAGER

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
Caller Service 4104
Farmington, New Mexico 87499

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 199 Huerfano Unit

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 325-4572.

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable): perf @ 2845 and spot a plug from 2845-2745 inside & outside 9 1/2" casing (Chaco)

spot a plug from 1800-1700 (Fruitland)

increase plug across Ojo Alamo to cover from 1370-1067

All plugs are to be ~~at~~ a minimum of 25 SX or 100' in length, whichever is greater (see #4 on attached sheet)

Office Hours: 7:45 A.M. to 4:30 P.M.