UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| Sundry Notices and Reports on Wel | als |
|--|--|
| 1. Type of Well GAS | 5. Lease Number SF-079709 019787 6. If Indian, All. or Tribe Name |
| 2. Name of Operator Meridian Oil Inc. 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 | 7. Unit Agreement Name Huerfano Unit 8. Well Name & Number Huerfano Unit #221 9. API Well No. |
| 4. Location of Well, Footage, Sec., T, R, M NESW Sec.13, T-25-N, R-10-W, NMPM /550/F5L +/560/F wt | 10. Field and Pool Basin Dakota 11. County and State San Juan Co, NM |
| Subsequent Report Recompletion Plugging Back Casing Repair | tion Change of Plans New Construction _ Non-Routine Fracturing |
| This well may have a casing failure. It is intenpick up an isolation packer, TIH, and se approximately 6000'. | et the pkr at \sim $\%$ |
| The well will be swabbed and returned to provide the swabbed and r | P P P P P P P P P P P P P P P P P P P |
| 14. I hereby certify that the foregoing is true and consigned Signed State (JAS) Title Regulatory Af | |
| APPROVED BYTitle CONDITION OF APPROVAL, if any: | Date APPROVED |