

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 6896

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

8. FARM OR LEASE NAME

El Paso Natural Gas Company

Nageezi

3. ADDRESS OF OPERATOR

9. WELL NO.

PO Box 990, Farmington, NM 87401

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

10. FIELD AND POOL, OR WILDCAT

See also space 17 below.)

At surface

1500'N, 1500'E

Basin Dakota

11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA

Sec. 12, T-25-N, R-9-W
NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6431'GL

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Plug back from Dakota to Gallup

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Due to well's inability to produce, it is planned to plug and abandon the Dakota and recomplete in the Gallup formation as follows:

Sting into EZ Drill at 6461' and squeeze with 15 sks. cement. Pull out of EZ Drill and spot a 15 sk. cement plug.

Set bridge plug at 6100'.

Selectively perforate and sandwater fracture the Gallup.



18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE Petroleum Engineer

DATE January 10, 1973

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: