

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYBUREAU OF LAND MANAGEMENT
Geological Instructions
Version 1001File No. _____
Bureau No. _____
LEASE OR CONVEYANCE AND SERIAL NO.

N00-C-14-20-27 27

B. INDIAN ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ GULF ☐ WELL ☐ WELL ☐ OTHER
2. NAME OF OPERATOR
TEXACO, Inc. Prod. Dept. West U.S.
3. ADDRESS OF OPERATOR
P. O. Box EE, Cortez, CO. 81321
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
NE $\frac{1}{4}$ NW $\frac{1}{4}$ Sec. 3
14. PERMIT NO. _____
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
510' from North line and 1980' from West line.

5712' DF

Navajo Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tribe "BR"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Tocito Dome Penn "D"

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S3, T25N, R18W

12. COUNTY OR PARISH; 13. STATE

San Juan New Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACURE TREAT	MULTIPLE COMPLETION
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco, Inc. plans to plug and abandon this well because it is uneconomical to produce and no potential for enhanced recovery exists. Navajo Tribe "BR" No. 1 IP'd at 2 BOPD and 18 BWPD. Texaco will abandon this well as follows:

- 1) Run free point survey; cut and recover 7" OD casing.
- 2) Fill hole with mud.
- 3) Spot and squeeze 35 sx cement from PBTD to 6350'.
- 4) Spot 75 sx cement across top of 7" OD csg. stub.
- 5) Spot 75 sx cement 2100' - 2300'.
- 6) Spot 70 sx cement 1550' - 1700' (across intermediate csg. shoe).
- 7) Spot 10 sx cement at surface.
- 8) Erect dry hole marker and clean location.

18. I hereby certify that the foregoing is true and correct.

SIGNED *[Signature]*TITLE **Field Foreman**DATE **12-1-77**

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

USGS(4) NMOGCC(3) GLE-ARM-JHP