

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MOO-C-14-20-5321

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER

2. NAME OF OPERATOR

Texaco, Inc.

Attention: **Mr. Bliss**

3. ADDRESS OF OPERATOR

P. O. Box 2100

Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any state requirements.
See also space 17 below.)
At surface

NE 1/4 NE 1/4 Sec. 16

660' FNL & 660' FEL, Sec. 16

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tribe "BT"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Yah-Teh-Hoy (Wildcat)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 16 T25N-R18W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, R, GR, etc.)

5669' GR

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Texaco plans to plug and abandon the subject using the following procedure:

1. Run free point survey, cut & recover 7" OD casing.
2. Spot 30 sacks cement from 6750' to TD.
3. Fill with mud.
4. Spot 50 sacks cement across top of 7" OD casing stub.
5. Fill hole with mud.
6. Spot 100 sacks cement from 4200' to 4350'.
7. Fill hole with mud.
8. Spot 100 sacks cement from 2450' to 2600'.
9. Fill hole with mud.
10. Set cement retainer @ 1570' (above bottom of 9-5/8" surface casing at 1620').
11. Displace 100 sacks cement through retainer w/tubing.
12. Fill hole with mud.
13. Spot 10 sacks cement at surface and erect standard dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED **Signed: Tommie Bliss**

TITLE **District Superintendent** DATE **Feb. 12, 1975**

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

USGS (3)

OGCC (2)

TB

ARM

CGH

The Navajo Tribe

Farm.

Aztec

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

G.P.O. : 1973- 780-622 /VIII- 148

