

DEPARTMENT OF THE INTERIOR (reverse side)  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-8007
2. NAME OF OPERATOR Union Oil Company of California		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 2620 - Casper, WY 82602		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1100' FSL & 1185 FWL		8. FARM OR LEASE NAME Federal
14. PERMIT NO.		9. WELL NO. 1 (M17)
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6493' G.L.		10. FIELD AND POOL, OR WILDCAT Basin Dakota
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T.25N., R.10W.
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

6225' T.D.

Released packer and pulled to 2200'. Set packer. Squeezed Cliff House perms, 2399-2409', 2425-2427', 2431-2433', 2441-2443', 2447-2455', and 2459' with 82 sacks regular cement to maximum standing squeeze pressure of 1700# with no bleed off. Top of cement plug at 2200'. Released packer, reversed tubing, and pulled out of hole laying down tubing. Cut off well head 4' below ground level. Placed 10 sack cement plug in top of casing. Welded plate on casing and installed dry hole marker.

Well plugged & abandoned September 16, 1977.



(Verbal approval to plug & abandon received from Mr. P. T. McGrath, District Engineer, U.S. Geological Survey, Farmington, New Mexico, on September 13, 1977.)

18. I hereby certify that the foregoing is true and correct

SIGNED

R. G. Ladd, Jr.

TITLE District Drilling Supt.

DATE 9-16-77

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

SEP 19 1977