



FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.
14-20-603-1228

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Central Bisti Unit

1. Type of Well

☒ Oil Well☐ Gas Well ☐ Other

2. Name of Operator

Central Resources, Inc. *Elm Ridge*

3. Address and Telephone No.

P.O. Box 1213, Bloomfield, New Mexico 87413 (505)-632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL, 2080' FEL, Sec 9, T25N, R12W

8. Well Name and No.

72

9. API Well No.

30-045-22945

10. Field and Pool, or Exploratory Area

Bisti Lower Gallup

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Central Resources, Inc. intends to plug the well in accordance with regulations. Production equipment will be removed and well will be plugged as specified. Perforate and squeeze will be used unless casing can be recovered over the specified interval where there is evidence cement is in place behind the casing.

Proposed Procedure:

- A.. Notify the Farmington BLM office at 505-599-8907 24 hours prior to commencement of plugging operations.
- B. Pull all retrievable downhole production equipment.
- C. Set a CIBP at 4888' and spot cement on top to 4838' to 4938'
- D. Set a 100' cement plug from 2486' to 2586' across Menefee top at 2536' inside and outside 4 1/2" casing
- E. Set a 100' cement plug from 1042' to 1142' across Pictured Cliffs at 1092' inside and outside 4 1/2" casing.
- F. Set a 100' cement plug from 682' to 782' across the Fruitland Coal at 732' inside and outside 4 1/2" casing.
- G. Set a cement plug from surface to 187' to 287' across the surface casing shoe at 237' inside and outside 4 1/2" casing
- H. Cut wellhead and install dry hole marker. Clear and remediate location.

Title Production Tech.

Date

February 14, 2001

14. I, the Patty Shelton

Si (This space for Federal or State office use)

Title

Date

2/15/01

Conditions of approval, if any:

Approved by