

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐  
2. NAME OF OPERATOR  
Southern Union Exploration Company  
3. ADDRESS OF OPERATOR Suite 1800, First  
International Bldg., Dallas, Tx. 75207  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17  
below.) Sec. 18, T25N, R13W  
AT SURFACE: 1650 FNL, 1650 FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE NM - 5459	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Grynborg Federal	
9. WELL NO. 1	
10. FIELD OR WILDCAT NAME Wildcat	
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Sec 18, T25N, R13W NMPMS	
12. COUNTY OR PARISH San Juan	13. STATE New Mexico
14. API NO. 30-045-22953	
15. ELEVATIONS (SHOW DE KDB AND WD) 6421 - GR	

(NOTE: Report results of multiple completion or zone  
change on Form 9-330.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,  
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and  
measured and true vertical depths for all markers and zones pertinent to this work.)\*

5-27-78 Tagged bridge at 1270'. Unable to clean out.  
5-28-78 Holiday.  
5-29-78 Prepared to swab well.  
5-30-78 Swabbed and flowed well. Swabbed 8 BW. Flowed 14 MCFD rate.  
5-31-78 Swabbed and flowed well. Swabbed 16 BW. Flowed 5 MCFD rate.  
6-1-78 Tagged fill-up at 1242'.  
6-2-78 Circulated well with nitrogen. CO to 1322'.  
Set tubing at 1304' and swabbed well dry.  
Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct K&A, Inc. Minerals Management.  
SIGNED [Signature] TITLE Area Manager DATE 6-21-78

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

\*See Instructions on Reverse Side

045 USGS/11-Southern Union/11-file