Form Approved

UNITED STATES

	Budget Bureau No. 42-R1424
	5/LEASE NOO-C-14-20-5210
1	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo
	7. UNIT AGREEMENT NAME
-	8. FARM OR LEASE NAME Jaquez
-	9. WELL NO.
_	10. FIELD OR WILDCAT NAME Wildcat DC
,	11. SEC., T., R., M., OR BLK. AND SURVEY OR SeC. 6-T25N-R11W
	12. COUNTY OR PARISH 13. STATE San Juan NM
•	14. API NO.

DEPARIMENT OF THE INTERIOR	1100 0 14 20 0210 2		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE N	AME	
	Navajo		
SUNDRY NOTICES AND REPORTS ON V	ELLS 7. UNIT AGREEMENT NAME		
Lo not use this form for proposals to drill or to deepen or plug back teaservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME		
	Jaquez -		
other Dry Hole	9. WELL NO.		
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME	10. FIELD OR WILDCAT NAME	
Tesoro Petroleum Corp.		Wildcat DC	
3. ADDRESS OF OPERATOR 2000 1st of Denver Plaza, Denver, CO 80		11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, Sec	space 17 AREA TOSH DITH	Sec. 6-T25N-R11W	
below.)	Sec. 6-125N-RIIW		
AT SURFACE: 800' FNL X 1820' FWL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: Same	() San Juan NM		
AT TOTAL DEPTH. Same	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE O	NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, 6203' GL, 6208' KB	AND WD)	
PRQUEST FOR APPROVAL TO: SUBSEQUENT REPO	RT OF:		
155T WATER SHUT-OFF			
FRACTURE TREAT	RECEIVED		
REPAIR MELL	(NGTE) Report results of multiple comple	tion or zone	
PULL OR ALTER CASING	NOV 2 Labange on Form 9-330.)		
THE COMPLETE	II C CTCI COICE CONT		
CHANGE ZONES	U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.		
ARANDON*	Tadamaron, IV. M.		
.er)			
17 DESCRIBE PROPOSED OR COMPLETED OPERAIDONS including estimated date of starting any proposed work measured and true vertical depths for all markers and zero.	It well is directionistly officed, kive stansariace for	ent dates ations and	
Pulled 2 3/8" tbg. Free point 4½", 10.5		ut	
cc = 1000 ft and $culled 2/1 its 44''$	III 5#. J-55. LING CSU. AND IAYEU		
- 1 /30/06/01\	. Itub ut bicinien cilis ac 1140	'GL	
TO at 1200!) Comont hole from 1158 ff	to surface w/ 120 SKS Class D C	1116.	
w/3% calcium chloride. Cement circulate	d to surface. Welded steel plate	onto	
surface csg. w/dry hole marker. Comple	e abandon on 10/27/81.	~ ~	
Surface Cade Ward Hole markers again.	101		

hate copy

JUL1 2 1991.

OIL CON. DIV. DIST, 3

Set @ _

@ ibsurface Safety Valve: Manu. and T

14 x 12/ , 134

TITLEDist. Oper. Mgr. DATE __10/30/8]_

(This space for Federal or State office use)

SERVICIED BY TVED BY THE APPROVAL IF ANY

NMOCO

FARMINGTON COPY

t is to pluiging of the well bore. tructions on Reverse Side by inder bond is retained until restoration is completed.