Form 3160-5 (November 1983) (Formerly 9-331)

## UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE\*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135 Expires August 31, 1985

Formerly 9–331) DEPARTMENT OF THE INTERIOR verse side)  BUREAU OF LAND MANAGEMENT			5. LEASE DESIGNATION AND SERIAL NO NM 33027		
SUNDRY NO	DTICES AND REPORTS  Opensals to drill or to deepen or plusication for Permit—" for suc	ON WELLS	0 IF INDIAN, ALLOTTEI	E OR TRIBE NAM	
I. OIL GAS WELL OTHER		4711 19 May 1. 1	7. UNIT AGREEMENT NA	N.E.	
NAME OF OPERATOR Hixon Development Company			8. FARM OR LEASE NAME South Bisti		
3. ADDRESS OF OPERATOR			9. WELL RO.		
PO Box 2810, Farmington, N.M. 87499			1		
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)</li> <li>At surface</li> </ol>			10. FIELD AND POOL, OR WILDCAT		
			Bisti Lower Gallup		
660' FSL, 660' FEL, 9	Sec. 3, T25N, R13W		Sec. 3, T25N,		
14. PERMIT NO. 18 ELEVATIONS (Show whether DF,		DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. GTATE	
	6297' GL		San Juan	N.M.	
16. Check A	Appropriate Box To Indicate	Nature of Notice, Report, or	Other Data		
NOTICE OF INTENTION TO.		SUBSEC	SUBSEQUENT REPORT OF:		
	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	FELL	
TEST WATER SHUT-OFF	Military by down town	FRACTURE TREATMENT	ALTERING CA	SING	
FRACTURE TREAT	MUUTIPLE COMPLETE				
[ ]	ABANDON*	SHOOTING OR ACHIEFING	ABANDONMEN	TT*	
FRACTURE TREAT	1	SHOOTING OR ACHIZING			

Hixon Development Company intends to convert this Bisti Lower Gallup well to water disposal pursuant to the New Mexico Oil Conservation Division Order No. SWD-385. A packer will be set on tubing at 4837'. The perforations from 4937' to 4947' will be acidized with 1000 gallons of 15% HCL acid and the well placed on injection. The casing will be tested and repaired if required prior to injection.

MAYO 4 1990 OIL CON. DIV.

18. I lereby certify that the foregoing is true an	d correct	
SCHOOL CLE	President President	DATE _ April 18, 1990
(This space for Federal or State office use)  APPROVED BY	APPROVED	
CONDITIONS OF APPROVAL, IF ANY:	esculptus.	APR 2.5.1990
		AREA MANAGER

\*See Instructions on Reverse Side

## Hixon Development Company Well Bore Diagram

WELL NAME South Bisti Well No. 1		
LOCATION 660' FSL, 660' FEL		SECTION 3 T 25 N R 13 N
		STATE New Mexico
		,
SURFACE CASING .		015 62071
		GLE_6291'
Hole Size: 12-1/4"		KBE
Casing: 8-5/8", J-55, 32#		
Casing Set @ 337' with 235 sks		DF
Class B containing 2% CaCl		WELL HISTORY
and 1/4 #/sk celloflake —		orbodo de la
		Spud date: 5/17/82
FORMATION TOPS		
Fruitland 1240'		Original owner: Southern Union
Pictured Cliffs 1295'		IPBOPDBWPD
Lewis Shale 1385'		
Mesa Verde 2000'		MCFDGOR
Mancos 3895'		Completion Treatment:
Gallup 4738'		
Tocito 4937'		
		CURRENT DATA
		JOHNENT DATA
		Pumping Unit
		Tubing
CEMENT TOP 1195'		Pump Size
PERFORATIONS		Rod string
4937'-47'		Remarks
		DV tool @ 3916'
DDD 50041		
PBD 5004'		
PRODUCTION CASING		
Hole Size: 7-7/8"		
Casing: 5-1/2", J-55, 15.5#	Tension Packer	
Casing Set @ 5044'		
1st stage: 175 sks 50/50 poz with	4837'	
2% gel, 7# salt		
2nd stage: 400 sks 65/35 poz with		
10% gel and tail in with 100		
sks Class B.		
	5050'TD	Date Last Revised: 3/27/90
	ID	Date Last 11041300. 3/21/30