UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENTO

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

Lease Designation and Serial No. SF 078056

	TENTO TENTO	D: 0. () SI 0/8030
	OF LAND MANAGEMENTS PTO	6. If Indian, Allottee or Tribe Name
	CES AND REPORTS ON WELLS	
Do not use this form for proposal Use "APPLICATI	s to drill or to deepen or reentry to a different rese ON FOR PERMIT" for such proposals	ervoir O., N. 7. If Unit or CA. Agreement Designation
SUBMIT IN TRIPLICATE		Central Bisti Unit
	as Well X Other Water Injection	8. Well Name and No. Central Bisti Unit #WI-88
2. Name of Operator		9. API Well No.
Giant Exploration & Production Company		30-045-25913
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area
P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325		Bisti Lower Gallup
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
380' FNL, 1650' FEL, Sec. 8, T25N, R12W		San Juan, New Mexico
	TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION		OF ACTION
	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
X Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	X Other Workover/Acidiz	zing Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and I og form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Giant Exploration & Production Company rigged up on the subject well to repair a tubing leak. The well was worked over as follows:

- 1) Tripped out of the hole with the tubing string.
- 2) Checked for fill. Set a cast iron bridge plug at 4840' to isolate injection into the upper set of Gallup perforations (4782'-4798'). Tested CIBP to 1500 psi, held pressure.
- 3) Acidized existing perforations with 1000 gal 15% HCl.
- 4) Installed a plastic coated injection tubing string with Arrowset 1 packer. Spotted packer fluid containing corrosion inhibitor/oxygen scavenger in the casing/tubing annulus. Set the packer at 4741'.

Performed an MIT to 350 psi for 30 minutes on 12/06/95. Pressure held. Test was witnessed by Ernest Cardona of the NMOCD. Resumed routine injection operations.

4. I hereby certify that the foregoing is true and con Signed Paul R. Williams	rrect Title Area Engineer	Date	DEC 0 8 1995
Paul R. Williams			
(This space for Federal or State office use)			
Approved by	Title	Date	
Conditions of approval, if any:		-	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department of the property of the propert

*See Instruction on Reverse Side

DEC 1 5 1995

I Come page NMOC

FARMINGTON DISTRICT OFFICE