Form 3160-5 (November 1994)

## UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004/0135 Expires July 37, 1996

5. Lease Serial No.

INM	NM-2	29005
-----	------	-------

	TOT	4.	Allottee or	OD 11	* T
16	It In	1120	Allottee of	· I mhe	Nam

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
	CATE – Other instruct	llon <b>\$</b> Oh revers	e side	7. If Unit or CA/	Agreement, Name and/or No.		
1. Type of Well	C Other			8. Well Name and	1 No		
Oil Well X Gas Well	Other			Ando Hixon #			
2. Name of Operator  Elm Ridge Resources, Inc.				9. API Well No.	· · · · · · · · · · · · · · · · · · ·		
	[2	b. Phone No. (include	area code)	30045-267	7:70		
3a. Address		505-632-3476	urea codej	10. Field and Pool, or Exploratory Area			
PO Box 189 Farmington, NM 8		700-032-3470		3	, or Dapioratory rava		
4. Location of Well (Footage, Sec., T., R. Sec. 31-T25N-R11W	, M., or Survey Description)			11. County or Pari	sh State		
990' FNL & 1980' FWL				11. County of Fairsit, State			
990 FIVE & 1900 FVVE				San Juan, New Mexico			
12. CHECK APPROPRIATE BOX(E	S) TO INDICATE NATURE O	F NOTICE, REPORT	Γ, OR OTHER DA	ATA			
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize	Deepen	Production (	Start/Resume)	Water Shut-Off		
A route of men	Alter Casing	Fracture Treat	Reclamation	, , , , , , , , , , , , , , , , , , ,	Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete		Other		
	Change Plans	X Plug and Abandon	Temporarily	Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispo	osal	<del></del>		
Testing has been completed. Final Abdetermined that the site is ready for final inspection. Bright Ridge Resources, Inc. proceeding can be recovered over of plugging operation. Set a Coff Mesa Verde from 1892' to 1 from 1210' to 1160', top @ 126885', top @ 935' inside and ou Cut off wellhead. Install dryhold	poses to plug and abando m the well and tubing will the specified interval. Pro IBP @ 4650'. Spot a 50' of 1992', top @ 1942' inside a 1993' inside and outside of 5 1993' tside 5-1/2 casing. Set a contract and remove	n the Ando Hixor be used to pump posed procedure: cement plug from and outside 5-1/2 -1/2 casing. Set a cement plug from	n #1 in accorda plugs. Perfora Notify BLM off n 4600' to 4650' casing. Set a s a 50' cement pl	nce with regula ite and squeez fice 24-hours p '. Set a 100' co 50' cement plud lug across top	ations. Production e will be used unless prior to commencement ement plug across top g across top of PC of FC from 935' to		
Certified Return Receipt # 700  14. Thereby certify that the foregoing is tr					<u> </u>		
Name (Printed/Typed)		Title		-	*		
	Grubelnik , 🔍 ,		Produc	tion Technicia	ាំ 🚉		
Signature 1	Date Ma		arch 27, 2002				
- Juneary	THIS SPACE F	OR FEDERAL OR S	TATE USE				
Approved by		Title	PIT	Date 4	18/02		
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to conduct	itable title to those rights in the subject operations thereon.	ect lease	FFO				
Title 18 U.S.C. Section 1001, makes it a cr fraudulent statements or representations as	ime for any person knowingly and wi	ilifully to make to any de	partment or agency of	f the United States a	ny false, fictitious or		