Form 3160-5 June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FØRM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 0468014

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well Brookhaven Oil Well XX Gas 8 Well Name and No. Name of Operator Brookhaven Fed. #1 9. API Well No. BHP Petroleum (Americas) Inc. 3 Address and Telephone No 30-045-27959 10. Field and Pool, or Exploratory Area 5847 San Felipe, Suite 3600, Houston, Texas 77057 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin Dakota 11. County or Parish, State 1620' FNL & 875' FWL (SW, NW) Section 20, T25N, R10W San Juan, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION X Notice of Intent Change of Plans) Abandonment New Construction Recompletion Plugging Back Non-Routine Fracturing MIG1 7 1993 Water Shut-Oft Casing Repair Conversion to Injection Altering Casing Final Abandonment N CON. DIV. Other Plug & Abandon Dispose Water-O (Note: Report results of multiple completion on Well DIST. 3 Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed stork. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* BHP P(A) proposes to plug and abandon the subject well within thirty days of receiving BLM approval. The proposed procedure is as follows: 1. RU Wireline Unit. Dump 10' of cmt. on top of CIBP @ 6050'. Run CBL from ±1625' to surface. 2. MIRU Workover Unit. ND wellhead and NU BOPE, PU 2-3/8" tubing. TIH to ±6030'. Circulate hole w/9.2 ppg. mud. 3. PU to 5135'. Mix and spot100' cmt. plug from 5131'to 5031'. (Gallup top @ 5081') PU to 2447'. Mix and spot100' cmt. plug from 2447' to 2347'. (Mesaverde top @ 2397') PU to 1590'. Mix and spot 100' cmt. plug from 1590' to 1490'. (Pictured Cliffs top @1540')
PU to 1200'. Mix and spot 100' cmt. plug from 1200' to 1100'. (Fruitland top @1150')
PU to 703'. Mix and spot 100' cmt. plug from 703' to 603'. (Ojo Alamo top @653') PU to 550'. Mix and pump 250' cmt. plug from 550' to 300'. (Fresh water sands; surface casing shoe @ 351') PU to 50'. Mix and pump cmt. to surface. TOOH w/remaining tubing. Top off well as necessary w/cmt. 4. ND BOPE. Cut off wellhead and install dry hole marker. PROCEDURE CONTINUED ON NEXT PAGE SEE ATTACHED FOR 14. I hereby cerafy that the foregging is true and correct (This space for Federal or State office use) Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unit Sacratic also Managed Contents statements

or representations as to any matter within its jurisdiction

Form	3160-5
(June	1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 0468014

Water Shut-Off

Dispose Water

Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

6. If Indian, Allottee or Tribe Name

Use "APPLICATION FOR	R PERMIT—" for such proposals	
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Wall Gas Well Other 2. Name of Operator		Brookhaven 8. Well Name and No. Brookhaven Federal #1
BHP Petroleum (Americas) Inc. 3. Address and Telephone No.		9. API Well No. 30-045-27959
5847 San Felipe, Suite 3600, Houston, Texas 77057 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area Basin Dakota
1620' FNL & 875' FWL (SW,NW) Section 20, T25N,R10W		11. County or Parish, State San Juan, New Mexico
2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO)N
XX Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Casing Repair

PLUGGING PROCEDURE CONTINUED.

Final Abandonment Notice

5. If the CBL indicates there is no cement across the intervals 703'- 603', 550'-300', & 50'to surface, the casing will be shot within 10' of the cmt. top. The bradenhead will be opened and cmt. will be circulated from the perfs to the surface both inside and outside the casing.

RECEIVED BLM 93 JUL 30 PM 3: 1:

14. I hereby offitify that the foresting is true and correct Signed M	Title Regulatory Affairs Rep.	Date	
(This space for Federal or State office use)	Title	Date	
Approved byConditions of approval, if any:	Title NWOCO	Date	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR

医生物自然的 医物理障碍性的

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Hell: / Brookhaven Federa/

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):
 - 1) It is required that a minimin of 35' of cement be placed on top of the CIBP if a dump boile is used. (50' minimum it spothed them to being)
 - 2) Move Mesaverde plug-- (Top of MV D 3062) Plug from 3/12' to 30/2'
 - 3.) Move Fruitland Pluy -- (Top of Fruitland 2 1331') Pluy from 1381' to 1281'
- (0) Oso Alamo pluy is to be from 860' to 602'.

 Office Hours: 7:45 a.m. to 4:30 p.m. (0) Alamo Top 2652' 64m, 2810')

Note! From CBL, the annulus space is to contain coment where place are required.

Ē