asing S sg.Perf.	790/N; 1850/ —w	Cu. ft.		w				w	DCu. ft. S×T.	P	B @	
·	BO/D MCF/D After	Hrs. SICP		After		1st Del. <u>Gas</u> 1st Del. <u>Oil</u>				T Gas		
	TOPS		NITD X		Well Log		TEST DATA				··	
Ojo Alamo		C-103	, /	Plat	X	Schd.	PC	Q	PW	PD	D	Ref.No
Kirtland		C-104		Electric Log		1			-	· · ·	-	Kei.140
ruitland			· · · · · · · · · · · · · · · · · · ·	C-122	· · · · · · · · · · · · · · · · · · ·	1		 	 	-	-	 -
Pictured Cliffs		Ditr		Dfa		1		 	 			
hacra		Datr		Dac		 			 			 -
liff House				и	 			<u> </u>	 			
/lenefee		1				ļ		·				
oint Lookout		1							ļ	<u> </u>	ļ	┷
lancos		1				 	-		-		ļ	
allup		1				 				ļ		
reenhorn		1							 			
akota		1							ļ		ļ	↓
ntrada		1				 						
		MIXON			Acres/o							
		VXIXON			Acres W/320	# . I			1			1

E. Bisti Coal 31 #1 B-31-25N-11W

Giant Explor.& Prod.



United States Department of the Interior

TAKE
PRIDE IN
AMERICA

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway

Farmington, New Mexico 87401 NOO-C-14-20-5579 et al. (WC) 3162.3-1 (019)

Giant Exploration & Production Company P.O. Box 2810 Farmington, NM 87499

OCT. 1 6 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. 1 Bisti Coal 27 Com, sec. 27, T. 25 N., R. 12 W., San Juan Co., NM lease NOO-C-14-20-5579.
- 2. 1 East Bisti Coal 31, sec. 31, T. 25 N., R. 11 W., San Juan Co., NM lease NM-76857.
- 3. 331 Carson Unit 23, sec. 23, T. 25 N., R. 12 W., San Juan Co., NM lease SF-078067.
 - 4. 1 Buena Suerte 14K Com, sec. 14, T. 25 N., R. 11 W., San Juan Co., NM lease 14-20-603-1431.
- 5. 323 Carson Unit 20, sec. 20, T. 25 N., R. 11 W., San Juan Co., NM lease SF-078061.

As discussed with Earlene Bickford of your company on October 10, 1991 the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Is John L. Keller

John L. Keller Chief, Branch of Mineral Resources

Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410 BIA, Window Rock

ABANDONED LOCATIONS

