Form 3160-5 (November 1983) (Famerly 9-331)

JNITED STATES BUBMIT IN TRIPLICATES Other Instructions on re OTHE INTERIOR verse side) **JNITED STATES**

Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

•	LEASS DESIGNATION		XO
	NM/0116	39	

BUREAU	OF LAND	MANAGEMENT	
			_

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or pitches to differ regrets.

6. IF INDIAN, ALLOTTER OR TRIBE NAME

SUBSEQUENT REPORT OF:

Use "APPLI	CATION FOR PERMIT—" for supproposal L				
OIL CAS Y OTHER	DEC 1 3 1985	7. UNIT AGREEMENT NAME			
NAME OF OPERATOR		8. FARM OR LEASE NAME			
E. L. Fundingslan	ad BUREAU OF LAND MANAGEMENT	Sunical D			
ADDRESS OF OPERATOR	FARMINGTON RESOURCE AREA	9. WELL NO.			
7400 E. Orchard H	Rd. St-240 Englewood Co., 80111	2			
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)		10. PIBLD AND POOL, OR WILDCAT			
At surface	Basin Dakota				
890' FNL 8	% 790' FEL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
RECEIVED		19-26N-7W			
4. PERMIT NO.	15. BLEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISE 13. STATE			
DEC 0.5 1985	6188 GR	Rio Arriba NM			
6. Charle A	Appropriate Box To Indicate Nature of Notice Panest as				

BUREAU OF LAND MANAGEMENT INTENTION TO : FARMINGTON RESOURCE AREA TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE PRACTURE TREATMENT ALTERING CASING

XXSHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS (Other) (Note: Report results of multiple completion on Well Completion or Recompletion Beport and Log form.) (Other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) *

Operator plans to permanently abandon this well as follows:

- 1. Place a 100 sack (118 cu. ft.) Class "B" neat cement plug from 6681' to 5330'.
- 2. Place a 25 sack (29.50 cu. ft.) Class "B" neat cement plus at surface.
- 3. Squeeze the braiden head with 25 sacks (29.50 cu. ft.) Class "B" neat cement.
- 4. Install dry hole marker.

Operations to start within 90 days of approval from BLM.

United States any false, fictitious or fraudulent statements or representations as to any matter within a

	DEC 19 1985
	OIL CON. DIV.
18. I hereby cartify that the foregoing is true and correct SIGNEDR D. Simmons TITLE Agent	DATES A12-3-85
(This space for Federal or State office use) APPROVED BY	DA DEC 1 7 1985
*See Instructions on Reverse Side	Johnskille Kin Walla Wallager FARMINGTON HEDD JACE AHSA
Stile 18 U.S.C. Section 1001, makes it a crime for any person in the Cand willfully United States may false distribute or froudulest eastern person in the Cand willfully	y to make to any department or agency of the

្រុមាភ្បៈទោករដ្ឋារ ប្រាស្ថិ Dlawar 60**0** Familiation, New Mexico 87499-00600

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 2 Sunical D

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
- 3. Blowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Surface Management Agency for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.

5. The following modifications to your plugging program are to be made (when applicable):

applicable):	o (271,-1	P1	inside	& Cutsic	10 4/2	Casi	z 3765 - 3665 3030 - 2130 *
Mescverde	Pert	(a)	3/65	108	,,,,	17	"	"	3030'-2130'
Chack	Ħ	н	3030'	"	• •				2170'-1768'
Pictured Cliffs Fruitland	4 11	11	2170'	11	11	••			1414-1314'
Ojo Alamo		0	1414'	11	1,	"	11	•	•

Office Hours: 7:30 A.M. to 4:15 P.M.