



STATE OF NEW MEXICO  
**ENERGY AND MINERALS DEPARTMENT**  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS  
GOVERNOR

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

October 6, 1987

Mr. Ed Barber  
Mobil Producing TX & NM, Inc.  
P.O. Box 778  
Farmington, NM 87499

Re: Jicarilla H #5 M-11-26N-3W  
Jicarilla D #7 M-13-26N-3W  
Jicarilla E #4 M-11-27N-3W  
Jicarilla F #1 B-22-27N-3W  
Jicarilla F #5 M-23-27N-3W  
Jicarilla G #4 M-26-27N-3W  
Jicarilla F #6 A-27-27N-3W  
Jicarilla G #1 A-35-27N-3W  
Jicarilla G #3 M-35-27N-3W

Dear Mr. Barber:

Annual packer leakage tests on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut in both zones for a minimum of 3 days. Blow the higher pressured zone to the atmosphere or through a separator for as long as it takes to drop the pressure to at least 50 PSI less than the shut in zone.

Notify this office at least 24 hours prior to tests, so we may provide a witness.

Your truly,

Charles Gholson  
Deputy Oil & Gas Inspector

CG/dj

xc: Well Files