

F. Loc. 1650/S; 1090/W Elev. 6515 DF Spd. 5/28/54 Comp. 7/9/54 TD 3098 PB
 Casing S 9-5/8 @ 105 W 125 Sx. Int. @ W Sx. Pr. 52 @ 3012 W 150 Sx. T. 1 @ 3080
 Csg. Perf. SOF 3012-3098 w/6000 G. 3400 # Prod. Str. T

I.P. 1374 MCF/D After 3 Hrs. SICP 910 PSI After 23 Days GOR Grav 1st Del. 6/18/54 EPNG

TOPS		NITD	I	Well Log	I	TEST				DATA		
						Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-102		Plot	I							
Fruitland		C-103		Electric Log	I							
Pictured Cliffs	<u>3011</u>	C-104	I	C-110	I	<u>54</u>	<u>695</u>	<u>92</u>	<u>248</u>	<u>250</u>	<u>92</u>	
Cliff House						<u>54</u>					<u>81</u>	
Menefee		Ditr		Dfa	<u>11</u>	<u>24/55</u>	<u>473</u>	<u>35</u>	<u>225</u>	<u>237</u>	<u>34</u>	
Point Lookout		Datr		Dac	<u>6</u>	<u>7/56</u>	<u>469</u>	<u>44</u>	<u>256</u>	<u>235</u>	<u>46</u>	
Mancos		Remarks				<u>12/57</u>	<u>447</u>	<u>27</u>	<u>250</u>	<u>224</u>	<u>20</u>	
Tocito						<u>7/52</u>	<u>421</u>	<u>26</u>	<u>257</u>	<u>211</u>	<u>20</u>	
Dakota						<u>9/25/54</u>	<u>407</u>	<u>19</u>	<u>215</u>	<u>207</u>	<u>20</u>	
Morrison						<u>10-6-54</u>	<u>363</u>	<u>17</u>	<u>230</u>	<u>182</u>	<u>21</u>	
Entrada						<u>3/5</u>	<u>400</u>	<u>25</u>	<u>200</u>	<u>180</u>	<u>20</u>	XM
						<u>2-26-55</u>	<u>405</u>	<u>16</u>	<u>245</u>	<u>220</u>	<u>9</u>	
						<u>7/3/54</u>	<u>392</u>	<u>16</u>	<u>200</u>	<u>314</u>	<u>9</u>	
PCD	<u>3504</u>				<u>160</u>							

P
 o
 o
 l So B1 PC Co. RA s 34 T. 27N R 6W U. L Over EPNG Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec.
 Lse. Reuter No. 1