

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079364
Unit Rincon

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

JUN 7 1958

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 30, 1958

Well No. 1 is located 990 ft. from N line and 990 ft. from E line of sec. 30

NW SE SE Sec. 30
(1/4 Sec. and Sec. No.)
South Blanco - Dakota
(Field)

27N 6W
(Twp.) (Range)
Rio Arriba
(County or Subdivision)


NMPN
(Meridian)
New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6648 ft. KB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6/17/58 an Otis type "B" 16/64" bottom hole choke was set in an Otis "J" landing nipple at 7536 FB. This was done to eliminate freezing in the well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXAS NATIONAL PETROLEUM CO.,

Address 405-1/2 W. Broadway

Peru, W. V.

By D. E. A. Johnson
D. E. A. Johnson
Title Area Manager