Form 9-331a (Feb. 1951)



## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No	080670

Unit Sen Aven 27-4 Unit 14-08-001-1054

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DOI!!	CHRSEOHENT REPORT OF	WATER SHUT-OFF
NOTICE OF INTENTION TO DRILL		SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO CHANGE PLANS		ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPA		RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CA		istory <u>19</u> 5
NOTICE OF INTENTION TO ABANDON WELL		
(INDICATE ABOVE	BY CHECK MARK NATURE OF REPORT, NOTICE, OF	
		February 27 , 1959
JE Sec. 29	705 ft. from \[ \begin{align*} N \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	• ***
(1/4 Sec. and Sec. No.)	(Twp.) (Range) (Meric	lian)
(Field)	(County or Subdivision)	(State or Territory)
Spud date 1-7-59. On 1-7-59 Total Depth 18		
Spud date 1-7-59. On 1-7-59 Total Depth 18 Res 4 joints 10 3/4", 32.7 Best cement. Did not cir	e sands; show sizes, weights, and lengths of prop g points, and all other important proposed work)  O'.  5# Armee S.V. casing (16).')  culate cerant. Filled up be	set at 172' w/200 sacks
Span date 1-7-59. On 1-7-59 Total Depth 18 Ran 4 joints 10 3/4", 32.7 Rest cement. Did not cir Rest thru 1" tubing. Cir Held 500% for 30 minutes.	e sands; show sizes, weights, and lengths of prop g points, and all other important proposed work)	set at 172' w/200 sacks ackside w/100 sacks
Spud date 1-7-59. On 1-7-59 Total Depth 18 Ras * joints 10 3/4", 32.7 Rest cement. Did not cir Rest thru 1" tubing. Cir Reld 500% for 30 minutes.  I understand that this plan of work must re ompany  B1 Paso Natural Company	e sands; show sizes, weights, and lengths of prop g points, and all other important proposed work)	set at 172' v/200 sacks ackside v/100 sacks
Spud date 1-7-59. On 1-7-59 Total Depth 18 Res 4 joints 10 3/4", 32.7 Seet cement. Did not cir Rest thru 1" tubing. Cir Held 500% for 30 minutes.  Tunderstand that this plan of work must recompany	e sands; show sizes, weights, and lengths of prop g points, and all other important proposed work)  O'.  Si Armee S.V. casing (161')  culate ceasant. Filled up be culated approx. 15 sacks.	set at 172 v/200 secks ackside v/100 secks  ey before operations may be commenced.